UNDERGROUND STORAGE TANK
Tightness Testing Checklist

The purpose of this form is to certify the proper tightness testing of underground storage tank (UST) systems including connected underground piping. Tightness testing shall be conducted in accordance with Chapter 173-360 WAC.

This Tightness Testing Checklist shall be completed and signed by a Licensed Tightness Testing Supervisor. The supervisor shall be on site when all tank tightness testing activities are being conducted. The firm which employs the licensed supervisor shall also be licensed by the Washington State Department of Ecology as a Service Provider.

A separate checklist must be completed for each UST system (tank and associated piping) tightness tested, except that separate UST systems tightness tested at one site may be reported together by photocopying page 2 and 3 of this form and completing these pages separately for each UST system. The completed checklist should be mailed to the following address within 30 days of completion of tightness testing:

DEPARTMENT OF ECOLOGY
UNDERGROUND STORAGE TANK SECTION
P. O. BOX 47655
OLYMPIA, WA 98504-7655

For further information about completing this form, please contact the Department of Ecology UST Section.

The tank owner or operator must report a failed tightness test as a suspected release to UST staff at the appropriate Ecology regional office within 24 hours.

1. UST SYSTEM OWNER AND LOCATION

UST Owner/Operator: ROBERT RAMSEY

Owners Address: 2520 W. WASHINGTON AVE. SUITE 200
Street — P.O. Box

YAKIMA — WA — 98903
City — State — Zip+4 (required)

Telephone: (509) 452-1510

Site ID Number (on Invoice or available from Ecology if tank is registered): N/A - YAKIMA INDIAN NATION

Site/Business Name: EAGLE STOP AND SAVE

Site Address: 50 W. WAPATO ROAD — YAKIMA
Street — County

WAPATO — WA — 98952
City — State — Zip+4 (required)

2. TIGHTNESS TESTING PERFORMED BY:

Firm: K.T.C.-KENNEDY TESTING CO.

Service Provider License Number: 74738

Address: 2418 6TH AVE. — NONE
Street — P.O. Box

CLARKSTON, — WA — 99403
City — State — Zip+4 (required)

Telephone: (509) 758-0679 OR (800) 682-7027

Licensed Supervisor: BILL G. TALBOTT / OWNER

Supervisor License Number: 74738

K.T.C. TESTING CO.
CLARKSTON, WA 99403
(800) 682-7027

PRECISION TANK & LINE TEST RESULTS

Invoice Address:

EAGLE STOP AAND SAVE
2520 W WA AVE SUITE 200
YAKIMA, WA 98903

Tank Location:

EAGLE STOP AND SAVE
50 W. WAPATO ROAD
WAPATO, WA. 98952

W.O.#: 196

I.D. Number: N/A
Technician:BGT
Tech.#:94255 Van#:001

Date: 12-27-95 Time Start: 05:27 End: 06:27 County: YAKIMA
Facility Phone#: (509) 877-7122 Groundwater Depth: 12',+ Blue Prints: N/A
Contact: MR. DUSTIN RAMSEY Date;Time system was filled: 12-26-95/21:00

Tank	Tank Capacity	Product	Tank	Fill/Vent Vapor Lines	Product Line	Type Of Vapor Recovery	Inches of Water/Tank	Pump Type	Tank Material
1									
2	12K	REG-UNL	PASS	N/A	N/A	N/A	-0-	TURB.	SWC
3									
4									
5									
6									

SITE LOG	TIME
Set Up Equip:	04:10
Bled Product Lines:	N/A
Bled Vapor Lines:	N/A
Bled Vent lines:	N/A
Bled Turbine:	YES
Bled Suction Pump:	N/A
Risers Installed:	N/A

a) This system and method meets the criteria set forth in NFPA #329.
b) Any failure listed above may require further action, check with all regulatory agencies.

Certified Technician Signature : Bill G. Talbott

Date : 12-27-95

additional tanks you may photocopy this form prior to completing.

3. TANK AND TESTING INFORMATION

1. Tank ID Number (as registered with Ecology): -2- 2. Date Installed: 1989

3. Tank capacity in gallons: 12,000 4. Date of tightness test: 12-27-95

5. Last substance stored: REGULAR UNLEADED 6. Is tank compartmentalized? NO

7. Tank is: X single wall ____ double wall

8. Reason for conducting tightness test:

X To comply with leak detection requirements in UST rules

____ To bring temporarily closed tank back into service

____ Tank or piping repair

____ Other (describe) _____

9. Type of test conducted:

X Tank tightness test only

____ Line tightness test only

____ Tank and lines tested separately

____ Total system test (tank and lines tested together)

10. Test method type:

X Overfill

____ Underfill volumetric

____ Nonvolumetric

11. Tightness testing method(s) used (indicate if more than one method was used - see note following item 12):

Test method name/version (TANK TESTER) A.E.S. SYSTEM II (VERSION 1)

Test method manufacturer A.E.S. ENSERVCO, INC./A.E.S.=Associated Environmental System

12. If a tank tightness test was conducted, indicate the percentage of tank volume that was filled with product during the test: 100%

Note: A tank must be tested up to the product level limited by the overfill prevention device. If an overfill prevention device is not installed, a tank must be tested *up to the 95% full level.* When underfill volumetric testing methods are used, the tank must be: 1) filled with product to the 95% full level or 2) the portion of the tank above the product level must be tested using a nonvolumetric method which meets performance standards, for tightness testing.

13. Indicate the method used to determine if groundwater was present above the bottom of the tank during the test (for single wall tanks): 12'+ LOCAL KNOWLEDGE

4. CHECKLIST

The following items shall be initialed by the licensed supervisor whose signature appears below.

	Yes	No	NA*
1. Has the tightness testing method used been demonstrated to meet the performance standard specified in the UST rules for the conditions under which the test was conducted? (e.g., detecting a 0.10 gallon per hour leak rate with probability of detection of at least 95% and a probability of false alarm of no more than 5%) *Note: A copy of Ecology's policy for demonstrating that leak detection methods meet performance standards may be obtained by contacting Ecology's UST section in Olympia.*	BGT X		

*Item not applicable

(checklist continues on page 3)

Invoice No.: 196 Date: 12/27/95 Time : 05:27:57
Technician: BGT Tank: NO.2/SWC Tank Diameter(in): 94
Volume(gal): 12000 Grade Level(in): 142 Product Level(in): 120
Water Level On Tank(in): 0
Specific Gravity: .75 Coefficient Of Expansion: 0.0006802
Calibration Value(ml): 200 Channel: 1
Level Segment From: 110 To 300 Temp Segment From: 110 To 300



Change In Calibration Zone = 9 Calibration Unit(gal/unit) = 0.00578
Starting Temperature (F): 40.429 Head Pressure(col/in (Btm)): 90.0
Surface Area(sq. in): 133.5 Temp. Change(F/h) : 0.022

Level volume(gph): 0.194
Temp. volume(gph): 0.180 Product Line(gph): N/A
Net change(gph) : 0.014
==========

Result ---> PASS P/L ---> NONE

** Notes **

EAGLE STOP AND SAVE / 50 W. WAPATO ROAD / WAPATO, WASHINGTON 98952
TANK NO.2 IS A 12,000 GALLON REGULAR UNLEADED GAS TANK.
THIS IS A FULL SYSTEM TEST AT 120", WITH A 200 ML. CAL. / TANK DIAMETER IS 94".
GRADE LEVEL IS AT 142" - GRADE LEVEL BEING MEASURED TO THE TOP OF THE FILL PIPE.

W. WapaTo Road

P= Unleaded Plus

U= Reg- Unleaded

S= Super Unleaded



Eagle STop and Save

50 W. WapaTo Road

WapaTo Wa 98952



	Yes	No	NA*
2. Have all written testing procedures developed by the manufacturer of the testing equipment and method been followed while the test was being set up and conducted?	BGT X		
3. Was the product level in the tank during the test within the limitations stated in the evaluation results used to demonstrate that the tightness test method meets performance standards?	BGT X		
4. Was the waiting period between the addition of product to the tank and the beginning of the test at or above the minimum waiting period stated in the evaluation results?	BGT X		
5. If groundwater was present above the bottom of the tank, have the testing procedures accounted for its presence? (for single wall tanks)	BGT X		
6. Have any loose fittings at the top of the tank been either tightened prior to beginning the test or accounted for when conducting the test and evaluating test results? (Applies to overfill methods only) *Exception: Interstitial space fitting on double wall tank should remain loose during test for interstitial space to vent to atmosphere.*	BGT X		
7. Have all vapor pockets either been removed prior to beginning the test or otherwise accounted for when conducting the test and evaluating test results?	BGT X		
8. Based on evaluating test results and conducting any retesting as necessary to obtain conclusive test results, the tightness test is: BGT XX Passed ____ Failed **Note: Inconclusive test results will not be considered as a valid tightness test for purposes of complying with UST release detection regulations.**			
9. If the tightness test is considered a failed test, has the owner/operator been notified of the test results? Note: The tank owner or operator must report a failed tightness test as a suspected release to UST staff at the appropriate Ecology regional office within 24 hours of being notified by the testing firm that a failed tightness test has occurred.			BGT X
10. If a failed test has occurred, results indicate that there is a leak in the: ____ Tank ____ Piping System If known, the leak rate is: ____ gallons per hour			

*Item not applicable

I hereby certify that I have been the licensed supervisor present during the above listed tightness testing activities and to the best of my knowledge they have been conducted in compliance with all applicable state and federal laws, regulations and procedures pertaining to underground storage tanks.

Persons submitting false information are subject to penalties under Chapter 173-360 WAC.

12-27-95 (Date) — Bill G. Talbott/Owner (Signature of Licensed Supervisor)

5. ADDITIONAL REQUIRED SIGNATURES

12-27-95 (Date) — Bill G. Talbott/Owner K.T.C. Testing (Signature of Licensed Service Provider firm (owner or person with signature authority))

12-29-95 (Date) — EAGLE STOP AND SAVE (Signature of Tank Owner or Authorized Representative)

ATTN. GEOFF KEELER
US ENVIRONMENTAL PROTECTION AGENCY
REGION 10
1200 SIXTH AVENUE
SEATTLE, WA 98101